

EXPEDITED SPCC SETTLEMENT AGREEMENT UNITED STATES ENVIRONMENTAL PROTECTION AGENCY REGION 7, 901 N. 5th ST., KANSAS CITY, KANSAS 66101

03 DEC 12 AM 9: 17

Facility Name: Wauneta Cooperative Oil Company (Respondent)

Location: 340 East 5th Street, Wauneta, NE 69033

Owner/Operator: Wauncta Cooperative Oil Company (Respondent)

On July 30, 2002, an authorized representative of the United States Environmental Protection Agency (EPA) conducted an inspection to determine compliance with the Oil Pollution Prevention (SPCC) regulations promulgated at 40 CFR Part 112 under Section 311(j) of the Clean Water Act (33 U.S.C. § 1321(j)) (the Act), and found that Respondent had violated regulations implementing Section 311(j) of the Act by failing to comply with the regulations as noted on the attached Spill Prevention Control and Countermeasure Inspection Findings Prevention Control and Countermeasure Inspection Findings, Alleged Violations, and Proposed Penalty Form (Form), which is hereby incorporated by reference.

If Respondent does not sign and return this Expedited Settlement as presented within 30 days of the date of its receipt, the proposed Expedited Settlement is withdrawn without prejudice to EPA's ability to file any other enforcement action for the violations identified in the Form.

This proceeding and the Expedited Settlement are under the APPROVED BY EPA: authority vested in the Administrator of EPA by Section 311(b) (6) (B) (i) of the Act, 33 U.S.C. § 1321(b) (6) (B) (i), as amended by the Oil Pollution Act of 1990, and 40 CFR § 22.13(b) and 22.18(b), published at 64 Fed. Reg. 40137 on July 23, 1999. The parties enter into this Expedited Settlement in order to settle the civil violations described in the Form for a penalty of \$ 550.00. This settlement is subject to the following terms and conditions:

EPA finds that Respondent is subject to the SPCC regulations, which are published at 40 CFR Part 112, and has violated the regulations as further described in the Form. Respondent admits that he/she is subject to 40 CFR Part 112 and that EPA has jurisdiction over Respondent and Respondent's conduct as described in the Form. Respondent does not contest the Inspection Findings, and waives any objections it may have to EPA's jurisdiction. Respondent consents to the assessment of the penalty stated above. Respondent certifies, subject to civil and criminal penalties for making a false submission to the United States Government, that the violations have been corrected and Respondent has sent a certified check in the amount of \$550.00 payable to the "Oil Spill Liability Trust Fund," to:

"Regional Hearing Clerk, Office of Regional Counsel, U.S. Environmental Protection Agency, 901 N. 5t Street, Kansas City, Kansas 66101".

Respondent has noted on the penalty payment check the docket number CWA-07-2003-0262 of this case.

(Do Not Make Check Out to Regional Hearing Clerk)

ENVIRONME STALL PROTECTION AGENCY-REGION VII DOCKET NO: CWA-07-208360262 HEARING CLERK This Expedited Settlement resolves Respondent's liability for Federal civil penalties for the violations of the SPCC regulations described in the Form. However, EPA does

not waive any rights to take any enforcement action for any other past, present, or future violations by Respondent of the SPCC regulations or of any other federal statute or regulations. By its first signature, EPA ratifies the Inspection Findings and Alleged Violations set forth in the

Upon signing and returning this Expedited Settlement to EPA, Respondent waives the opportunity for a hearing or appeal pursuant to Section 311 of the Act, and consents to EPA's approval of the Expedited Settlement without further notice.

This Expedited Settlement is binding on the parties signing below, and is effective upon the Regional Judicial Officer's signature.

Chief, Emergence Planning & Response Branch Superfund, Division

APPROVED BY RESPONDENT:

Name (print): Wante Coop Oil by Haveld Anderson

Title (print): manac

IT IS SO ORDERED:

Robert L. Patrick

Date Dec. 11. 2003

Regional Judicial Officer

INSTRUCTIONS ON REVERSE

INSTRUCTIONS

The United States Environmental Protection Agency ("EPA") has authority under Section 311 of the Clean Water Act to pursue civil penalties for violations of the Spill Prevention, Control and Countermeasures ("SPCC") regulations. However, EPA encourages the expedited settlement of easily verifiable violations of SPCC requirements, such as the violations cited in this Expedited Settlement Agreement.

You may resolve the cited violations quickly by signing and returning the Expedited Settlement Agreement (Agreement) and paying the penalty amount within 30 days of your receipt of the Agreement. Failure to return the Agreement within the approved time does not relieve you of the responsibility to comply fully with the regulations, including correcting the violations that have been specifically identified by the inspector. If you decide not to sign and return the Agreement and not pay the penalty, EPA can pursue more formal enforcement measures to correct the violation(s) and seek penalties of up to \$11,000 per violation up to a maximum penalty of \$27,500.

You are required in the Agreement to certify that you have corrected the violations and paid the penalty amount. The payment for the penalty amount <u>must</u> be in the form of a certified check payable to the "Oil Spill Liability Trust Fund," with the Docket Number of the Expedited Settlement Agreement on the <u>check</u>. The Docket Number is located at the top of the right column of the Agreement.

The Agreement and Payment of the penalty amount shall be sent via <u>certified</u> mail to:

Regional Hearing Clerk Office of Regional Counsel U.S. Environmental Protection Agency 901 N. 5th Street Kansas City, Kansas 66101

By the terms of the Agreement, you waive your opportunity for a hearing pursuant to Section 311 of the Clean Water Act. EPA will treat any response to the proposed Agreement, other than acceptance of the settlement offer, as an indication that you are not interested in pursuing this expedited settlement procedure.

If you have any questions, you may contact the EPA Region 7 SPCC Compliance Coordinator at (913) 551-7251.

Spill Prevention Control and Countermeasure Inspection Findings, Alleged Violations, and Proposed Penalty Form

(Note: Do not use this form if there is no secondary containment)

These Findings. Alleged Violations and Penalties are issued by EPA Region 7 under the authority vested in the Administrator of EPA by Section 311(b)(6)(B)(i) of the Clean Water Act, as amended by the Oil Pollution Act of 1990

Combania value		Docket Number: CWA			
Waung	em Coopers ave Oil Company	7 - 2 0 0 3 - 6 2 6 2 8 6 7			
Pacility	y Name	Date Date July 30, 2002			
Wauncia Coonerative Oil Company		July 30, 2002			
Address		Inspection Number			
340 Ξ	ast 5th Street	F Y - I N S P - C 2 - 0			
Cny		Inspector's Name			
Weuneta		Mare Callaghan			
State:	Zip Ceác:	EPA Approving Official:			
NE NE	69033	Robert W. Jackson			
Facility	Comacu:	Enforcement Contacts:			
Mr. Wyatt Croft		Bob Webber Phone Number: (913)551-7251 Alan Hancock Phone Number: (913)551-7647			
<u>(Wila</u> :	en the SPCC Plan review penalty exceeds	(d), (e); 112.5(a), (b), (c); 112.7 (b), (c), (d) \$\\$1.000.00 \text{ enter only the maximum allowable of \$1.000.00.}			
⊒ ∐ Pla	in not certified by a professional	asure Plan \$1.003.00			
_	minor certified by a professional engineer	300.00			
יטא. ע הות ר	management approval of plan				
⊒ Fia ⊐ -:	Plan not available for review				
_ PJa −	n not maintained on site (applies if facilit	y is manned at least eight (8) hours per day) 100.00			
」No _	evidence of three-year review of plan by	owner/operator			
No plan amendment(s) if the facility has had a change in: design, construction, operation, or maintenance which affects the facility's discharge potential					
] Air	nendment(s) not certified by a professiona	d engineer100.00			
] Ina	dequate or no prediction of equipment fai	lure which could result in discharges			
] Pla	n does not discuss appropriate containme	nt/diversionary structures/equipment			

Ciai	ming installation of appropriate containment/diversionary structures is impractical but					
	No contingency plan					
	The state of the s					
	Written Procedures and Inspection Records 112.7(e)(8)					
	Inspections required by 40 CFR Part 112 are not in accordance with written procedures developed for the facility					
<u>i</u>	Written procedures and a record of inspections are not signed by facility supervisor 5-340					
	Written procedures and a record of inspections are not made part of the plan					
	Written procedures and a record of inspections are not maintained for three years					
	Personnel Training and Spill Provention Procedures 112.7(e)(16)					
	No training on the operation and maintenance of equipment to prevent discharges					
	No training on the applicable laws, rules, and regulations					
	No designated person responsible for spill prevention					
	Spill prevention briefings are not scheduled and conducted periodically					
	Har, has madequate of no discussion of personnel training and spill prevention procedures 51.77					
FACILITY DRAINAGE, ONSHORE (excluding Production Facilities) 112.7(e)(1)						
	Valves used to drain diked areas are not of manual, open-and-closed design (note: flapper-type valves should not be used)					
	Pumps or ejectors not manually activated when diked storage areas drained					
	Drainage from undiked areas not into ponds, lagoons, or catchment basins, or no diversion systems to return spills to the facility					
	Plan has inadequate or no discussion of facility drainage					
	BULK STORAGE TANKS (excluding Production Facilities) 112.7(e)(2)					
	Material and construction of tanks not compatible to the material stored and the conditions of storage such as pressure and temperature					
	Secondary containment appears to be grossly inadequate					
	Materials of construction are not sufficiently impervious					
	Excessive vegetation which affects the integrity of the containment system					
	Walls of containment system are slightly eroded or have low areas					

Sylear valve not normally sealed closed Solece	*4	hen drainage from diked areas is to a storm drain, open water course, or lake or pond:
B years velve is not opened and or with cause a harmful discharge as defined in 40 CF1.110 100.00 A disputate records of drainage events are not maintained 50.00 Correction of the protected from corrosion or are not subjected to regular pressure testing 100.00 Partially burned tanks do not have burned sections protected from corrosion. 100.00 Adverground tanks do not have burned sections protected from corrosion. 100.00 Aboveground tanks do not have burned sections protected from corrosion. 100.00 Aboveground tanks not subject to periodic integray testing, such as visual, bydrostatic, and nonaestructive methods, one 50.00 Outside of trail, not frequently observed for signs of deterioration, leaks which might cause a spill, of are annihilation of oil inside dised area. 50.00 Steam return exhaust of internal heating cells which discharge into an onen water course not memoratored, passed through a settling tank, skimmer, or other separation system. 100.00 Records of inspections of aboveground tanks are not maintained 50.00 Tanks are not "fail-safe" engineered: No audible or visual high liquid level alarm, or 500.00 No high-level pump cut-off devices set to stop flow at a prodetermined tank content level, or 500.00 No fast response system for determining liquid levels, such as computers, telepulse or direct vision gauges. Disposal facilities which discharge plant effuents directly to navigable waters are not mornitored frequently to detect oil spills. 100.00 Wishlic oil leaks resulting in accumulations of oil it diked areas are not promptly corrected. 100.00 Mobile or portable storage tanks are not positioned to prevent spilled oil from reaching navigable water, or are in area subject to flooding. 100.00 Mobile or portable storage tanks are not positioned to prevent spilled oil from reaching navigable water, or are in area subject to flooding. 100.00 Plan has inadequate or no discussion of bulk storage tanks - 50.00 Burned piping not corrosion protected with protective wrapping, coating, or catho		and place was raive not normally sealed closed
Adequate records of drainage events are not maintained 50.60 Underground tanks are not protected from corrosion or are not adjected to regular measure tening 10.60. Partially burned tanks do not have burned sections protected from corrosion. 109.00 Anoweground tanks not subject to periodic integrity testing, such at visual bydrostant, and nonzestructive methods, etc. 20.00 Omaids of truit, not frequently observed for signs of deterioration, leaks which might course a spile, or accumulation of oil inside difficult area. 300.00 Steam return rectinates of internal heating cells which discharge into an onen water course nonmonitored, passed intrough a setting tank, skimmer, or other separation system. 100.00 Records of inspections of aboveground tanks are not maintained 55.00 Tanks are not "fail-safe" engineered: No audible or visual high liquid level alizant, or	, L] Runoff rain water not inspected and/or will cause a harmful discharge as defined in 40 CDF and
Underground tarits are not protected from corrosson or are not subjected to regular measure testing. 106,00 Partially burned tarits are not have burned sections protected from corrosson. 100,60 Aboveground tarits not subject to perhodic integrity testing, such as visual, bydrostatic, and prodestructive methods, etc. Outside of ten, not frequently observed for signs of deterioration, leads which might cause, a spile, or accumulation, of oil inside dired area. 309,00 Steam return reginals of internal heating cells which discharge into an open water course per monitored, passed through a settling tank, skimmer, or other separation system. 100,00 Records of inspections of aboveground tanks are not maintained 50,00 Tanks are not "fail-safe" engineered: No audible or visual high liquid level alarm, or 300,00 No high-level pump cutoff devices set to stop flow at a predetermined tank content level, or 300,00 No fast response system for determining liquid levels, such as computers, telepulse or direct vision gauges. 300,00 No testing of liquid level sensing devices to ensure proper operation 50,00 No testing of liquid level sensing devices to ensure proper operation 50,00 Disposal facilities which discharge plant effluents directly to navigable waters are not morniored frequently to detect oil spills. 100,00 Wisible oil leaks resulting in accumulations of oil in diked areas are not promptly corrected 300,00 Mobile or portable storage tanks are not positioned to prevent spilled oil from reaching navigable water, or are in area subject to flooding. 100,00 Secondary containment inadequate for mobile or portable storage tanks . 50,00 Plan has inadequate or no discussion of bulk storage tanks . 50,00 Plan has inadequate or no discussion of bulk storage tanks . 50,00 Plan has inadequate or no discussion of bulk storage tanks . 50,00 Plan has inadequate or no discussion of bulk storage tanks . 50,00 Plan has inadequate or no discussion of bulk storage tanks . 50,00 Plan has inadequate or no discussion of bulk storage tanks .	[Bypass valve is not opened and resealed under responsible supervision.
Putially baried tanks do not have buried sections protected from corrosion. 100.00 Aboveground tanks not subject to periodic integrity testing, such as visual, nydrostatic, and nonestructive methods, etc. 700.00 Outside of tank not frequently observed for signs of deterioration, leaks which might cause a spill, or accumulation of oil miside diked area. 300.00 Steam return /exhaust of internal heating colls which discharge into an open water course not mentiored, passed intrough a settling tank, skimmer, or other separation system. 100.00 Records of inspections of aboveground tanks are not maintained 50.00 Tanks are not "fail-safe" engineered: No audible or visual high liquid level alarm, or No ingh-level pump cutoff devices set to stop flow at a predetermined tank content level, or 300.00 No fast response system for determining liquid levels, such as computers, telepulse or direct vision gauges. No testing of liquid level sensing devices to ensure proper operation 50.00 Disposal facilities which discharge plant effluents directly to navigable waters are not mornitored irequently to detect oil spills. 100.00 Wisible oil leaks resulting in accumulations of oil if diked areas are not promptly corrected 300.00 Mobile or portable storage tanks are not positioned to prevent spilled oil from reaching navigable water, or are in area subject to dooding. 100.00 Plan has inadequate or no discussion of bulk storage tanks - 50.00 Plan has inadequate or no discussion of bulk storage tanks - 50.00 Beried piping not corrosion protected with protective wrapping, coating, or cathodic protection . 100.00 Corrective action not taken on ouried piping when corrosion damage found . 300.00		A dequate records of drainage events are not maintained
Aboveground tanks of 16th lave oursed sections protected from corrosion. 100,60 Aboveground tanks not subject to periodic integrity testing, such as visual, bydrostatic, and noncestructive methods, etc. Outside of ten i not frequently observed for signs of deterioration, leaks which might cause, a spill, or accumulation of oil miside dified area. 360,00 Steam return exchaust of internal heating coils which discharge into an open water course not monitored, passed through a setting tank, sichment, or other separation system. 190,00 Records of inspections of aboveground tanks are not maintained 56,00 Tanks are not "fail-safe" engineered: No audible or visual high liquid level alarm, or 300,00 No high-level pump cutoff devices set to stop flow at a prodetermined tank content level, or 300,00 No fast response system for determining liquid levels, such as computers, telepulse or direct vision gauges. 300,00 No testing of liquid level sensing devices to ensure proper operation 50,00 Disposal facilities which discharge plant effluents directly to navigable waters are not mornitored frequently to detect oil spills. 400,00 Wisibic oil leaks resulting in accumulations of oil if diked areas are not promptly corrected 300,00 Mobile or portable storage tanks are not positioned to prevent spilled oil from reaching navigable water, or are in area subject to dooding. 100,00 Secondary containment inadequate for mobile or portable storage tanks 500,00 Plan has inadequate or no discussion of bulk storage tanks - 50,00 Facility Transfer Operations, PUMPING, and IN-PLANT PROCESSES. ONSHORE	_	Underground tanks are not protected from correction or any
noncestructure methods, etc. Outside of tank not frequently observed for signs of deterioration, leaks which might cause, a sylli, or accumulation of oil inside diled area. Steam return ret		Partially buried tanks do not have buried sections pressure 16
Outside of tent not frequently observed for signs of deterioration, leaks which might eaus, a spili, or accumulation of oil inside difeed area. Steam return exchaust of internal heating coils which discharge into an open water course not monitored, passed through a setting tank, skimmer, or other separation system. Records of inspections of aboveground tanks are not maintained 50,000 Tanks are not "fail-safe" engineered: No audible or visual high liquid level alarm, or No high-level pump outoff devices set to stop flow at a predetermined tank content level, or 300,000 No fast response system for determining liquid levels, such as computers, telepulse or direct vision gauges. No testing of liquid level sensing devices to ensure proper operation. Disposal facilities which discharge plant effluents directly to navigable waters are not mornitored frequently to detect oil spills. Visible oil leaks resulting in accumulations of oil in diked areas are not promptly corrected. 300,000 Mobile or portable storage tanks are not positioned to prevent spilled oil from reaching navigable water, or are in area subject to flooding. Secondary containment inadequate for mobile or portable storage tanks. 500,000 Plan has inadequate or no discussion of bulk storage tanks. 500,000 FACILITY TRANSFER OPERATIONS, PUMPING, AND IN-PLANT PROCESSES, ONSHORE Buried piping not corrosion protected with protective wrapping, coating, or cathodic protection. 100,000 Corrective action not taken on buried piping when corrosion damage found. 300,006	<u> </u>	Above ground tanks not subject to periodic intensities.
Cause a spill, or accumulation of of, inside dized area. 300.00 Steam return rexhaust of internal heating ceils which discharge into an open water course nontrored, passed inrough a setting tank, skimmer, or other separation system. 193.00 Records of inspections of aboveground tanks are not maintained 50,00 Tanks are not "fail-safe" engineered: No audible or visual high liquid level alarm, or 50,00 No high-level pump cutoff devices set to stop flow at a prodetermined tank content level, or 300.00 No fast response system for determining liquid levels, such as computers, telepulse or direct vision gauges. 300.00 No testing of liquid level sensing devices to ensure proper operation 50.00 Disposal facilities which discharge plant effluents directly to navigable waters are not mornitored frequently to detect oil spills. 100.00 Wisible oil leaks resulting in accumulations of oil iff diked areas are not promptly corrected 300.00 Mobile or portable storage tanks are not positioned to prevent spilled oil from reaching navigable water, or are in area subject to flooding. 50.00 Secondary containment inadequate for mobile or portable storage tanks 500.00 Plan has inadequate or no discussion of bulk storage tanks 50.00 FACILITY TRANSFER OPERATIONS, PUMPING, AND IN-PLANT PROCESSES, ONSHORE Taminal connections of taken on buried piping when corrosion damage found 300.00 Taminal connections of taken on buried piping when corrosion damage found 300.00		
not monitored, passed through a setting calls which discharge into an open water course Records of inspections of aboveground tanks are not maintained 50.00 Tanks are not "fail-safe" engineered: No audible or visual high liquid level alarm, or 300.00 No high-level pump cutoff devices set to stop flow at a predetermined tank content level, or 300.00 No first response system for determining liquid levels, such as computers, telepulse or direct vision gauges. No testing of liquid level sensing devices to ensure proper operation 50.00 Disposal facilities which discharge plant effluents directly to navigable waters are not mornitored frequently to detect of spills. Visible oil leaks resulting in accumulations of oil in diked areas are not promptly corrected 300.00 Mobils or portable storage tanks are not positioned to prevent spilled oil from reaching navigable water, or are in area subject to flooding. Secondary containment inadequate for mobile or portable storage tanks 500.00 Plan has inadequate or no discussion of bulk storage tanks 500.00 FACILITY TRANSFER OPERATIONS, PUMPING, AND IN-PLANT PROCESSES, ONSHORE Buried piping not corrosion protected with protective wrapping, coating, or cathodic prote ction. 100.00 Corrective action not taken on buried piping when corrosion damage found 300.00		
Records of inspections of aboveground tanks are not maintained 50,00 Tanks are not "fail-safe" engineered: No audible or visual high liquid level alarm, or 300,00 No high-level pump cutoff devices set to stop flow at a predetermined tank content level. or 300,00 No fast response system for determining liquid levels, such as computers, telepulse or direct vision gauges. 300,00 No testing of liquid level sensing devices to ensure proper operation 50,00 Disposal facilities which discharge plant effluents directly to navigable waters are not mornitored frequently to detect oil spills 100,00 Visible oil leaks resulting in accumulations of oil in diked areas are not promptly corrected 300,00 Mobile or portable storage tanks are not positioned to prevent spilled oil from reaching navigable water, or are in area subject to flooding. 100,00 Secondary containment inadequate for mobile or portable storage tanks 500,00 Plan has inadequate or no discussion of bulk storage tanks 500,00 FACILITY TRANSFER OPERATIONS, PUMPING, AND IN-PLANT PROCESSES. ONSHORE Buried piping not corrosion protected with protective wrapping, coating, or cathodic protection. 100,00 Corrective action not taken on buried piping when corrosion damage found 300,06		Steam return /exhaust of internal heating coils which discharge into the
Tanks are not "fail-safe" engineered: No audible or visual high liquid level alarm, or No high-level pump cutoff devices set to stop flow at a predetermined tank content level. or 300.00 No fast response system for determining liquid levels, such as computers, telepulse or direct vision gauges. No testing of liquid level sensing devices to ensure proper operation 50.00 Disposal facilities which discharge plant effluents directly to navigable waters are not mornitored frequently to detect oil spills 100.00 Visible oil leaks resulting in accumulations of oil in diked areas are not promptly corrected 300.00 Mobile or portable storage tanks are not positioned to prevent spilled oil from reaching navigable water, or are in area subject to flooding. Secondary containment inadequate for mobile or portable storage tanks 500.00 Plan has inadequate or no discussion of bulk storage tanks 500.00 FACILITY TRANSFER OPERATIONS, PUMPING, AND IN-PLANT PROCESSES, ONSHORE Buried piping not corrosion protected with protective wrapping, coating, or cathodic protection. 100.00 Corrective action not taken on buried piping when corrosion damage found. 300.00		s said said the second of the
No audible or visual high liquid level alarm, or		anoveground tanks are not maintained
No direct communications between tank gauger and pumping station, or		- and the tan-sale engineered;
No direct communications between tank gauger and pumping station, or		No audible or visual high liquid level alarm, or
No fast response system for determining liquid levels, such as computers, telepulse or direct vision gauges. No testing of liquid level sensing devices to ensure proper operation. Disposal facilities which discharge plant effluents directly to navigable waters are not mornitored frequently to detect oil spills. Visible oil leaks resulting in accumulations of oil in diked areas are not promptly corrected. 300,00 Mobile or portable storage tanks are not positioned to prevent spilled oil from reaching navigable water, or are in area subject to flooding. 100,00 Secondary containment inadequate for mobile or portable storage tanks. 500,00 Plan has inadequate or no discussion of bulk storage tanks. 500,00 FACILITY TRANSFER OPERATIONS, PUMPING, AND IN-PLANT PROCESSES, ONSHORE Buried piping not cotrosion protected with protective wrapping, coating, or cathodic protection. 100,00 Corrective action not taken on buried piping when corrosion damage found. 300,00		No high-level pump outoff devices set to stop flow at a producerpined table company.
direct vision gauges. 300.00 No testing of liquid level sensing devices to ensure proper operation 50.00 Disposal facilities which discharge plant effluents directly to navigable waters are not mornitored frequently to detect oil spills 100.00 Visible oil leaks resulting in accumulations of oil in diked areas are not promptly corrected 300.00 Mobile or portable storage tanks are not positioned to prevent spilled oil from reaching navigable water, or are in area subject to flooding. 100.00 Secondary containment inadequate for mobile or portable storage tanks 500.00 Plan has inadequate or no discussion of bulk storage tanks 500.00 FACILITY TRANSFER OPERATIONS, PUMPING, AND IN-PLANT PROCESSES, ONSHORE Buried piping not corrosion protected with protective wrapping, coating, or cathodic protection. 100.00 Corrective action not taken on buried piping when corrosion damage found 300.00		No direct communications between tank gauger and puraping station and
No testing of liquid level sensing devices to ensure proper operation		ATM TEST TOSTIONS SVSTEMS for determining Disc. 11 Fig. 4
Disposal actifies which discharge plant effluents directly to navigable waters are not mornitored frequently to detect oil spills 100.00		DOM NO.
Visible oil leaks resulting in accumulations of oil in diked areas are not promptly corrected. 300.00 Mobile or portable storage tanks are not positioned to prevent spilled oil from reaching navigable water, or are in area subject to flooding. 100.00 Secondary containment inadequate for mobile or portable storage tanks 500.00 Plan has inadequate or no discussion of bulk storage tanks 500.00 FACILITY TRANSFER OPERATIONS, PUMPING, AND IN-PLANT PROCESSES, ONSHORE Buried piping not corrosion protected with protective wrapping, coating, or cathodic protection. 100.00 Corrective action not taken on buried piping when corrosion damage found 300.06 Terminal connections at transfer.		P is used in the contraction of the contraction of P
Secondary containment inadequate for mobile or portable storage tanks		$1000\mathrm{CeV}$
Secondary containment inadequate for mobile or portable storage tanks		Mobile or portable of accumulations of oil in diked areas are not promptly corrected300.00
Plan has inadequate or no discussion of bulk storage tanks	;	navigable water, or are in area subject to flooding.
FACILITY TRANSFER OPERATIONS. PUMPING. AND IN-PLANT PROCESSES. ONSHORE Buried piping not corrosion protected with protective wrapping, coating, or cathodic protection		Secondary containment inadequate for mobile or normable storage tables
FACILITY TRANSFER OPERATIONS. PUMPING. AND IN-PLANT PROCESSES. ONSHORE Buried piping not corrosion protected with protective wrapping, coating, or cathodic protection		Plan has inadequate or no discussion of bulk storage tanks
Buried piping not corrosion protected with protective wrapping, coating, or cathodic protection		50,00
Terminal connections at transfer.	FAC	ILITY TRANSFER OPERATIONS, PUMPING, AND IN-PLANT PROCESSES, ONSHORE (excluding Production Facilities) 112.7(e)(3)
Terminal connections at transfer.		David
Terminal connections at transfer.		Dutted piping not corrosion protected with protective wrapping, coating, or cathodic protection 100.00
$I = I = I \cup $		corrective action not taken on buried piping when corrosion damage found
		Terminal connections at transfer points on not-in-service or standby pipelines are not capped or blank-flanged and marked as to origin

\equiv	Pine supports are not properly designed to minimize abrasion and corresion, and allow for expansion and contraction.	To a c
	A hoveground valves and pipelines are not inspected regularly	
	Periodic pressure testing of the valves and pipelines is not conducted	
	Vehicle traffic not warned verbally or by appropriate signs of aboveground piping	
	Plan has inadequate or no discussion of facility transfer operations, pumping, and in-plant processor	
FAC	THE TY TANE CAR AND TANK TRUCK LOADING/UNLOADING RACK, ONSHORE (112.7(e)(4)	
	In adequate, secondary containment, and/or rack drainage does not flow to calchment basin, treatment system, or quick drainage system.	560,00
	Containment system does not hold at least the maximum capacity of the largest single compariment of any tank car or tank truck	346 Jul.
	There is no interlocked warning light, physical barrier system, or warning signs to prevent vehicular departure before complete disconnect from transfer lines.	
	There is no inspection of lowermost drains and all outlets prior to filling and departure of any tank car or tank truck.	
	Plan has inadequate or no discussion of facility tank car and tank truck loading unloading rack	
SEÇ	UNITY (excluding Production Facilities) 112.7(e)(9)	
	Facility not fully senced and entrance gates are not locked and/or guarded when plant is unattended or not in production.	:= 160.65
	Master flow and drain valves that permit direct outward flow of tank's contents to the surface are not secured in closed position when in a non-operating or standby status	
	Loading and unloading connection(s) of pipelines are not capped or blank-flanged when not in service	
	Facility lighting not commensurate with the type and location of facility to facilitate the discovery of spills during hours of darkness and to deter vandalism.	
	Plan has inadequate or no discussion of facility security	
		er nev

TOTAL S 550.00

IN THE MATTER OF Wauneta Cooperative Oil Company, Respondent Docket No. CWA-07-2003-0262

CERTIFICATE OF SERVICE

I certify that the foregoing Expedited SPCC Settlement Agreement was sent this day in the following manner to the addressees:

Copy hand delivered to Attorney for Complainant:

Kristina Kemp
Assistant Regional Counsel
Region VII
United States Environmental Protection Agency
901 N. 5th Street
Kansas City, Kansas 66101

Copy by Certified Mail Return Receipt to:

Harold Anderson, Manager Wauneta Cooperative Oil Company 340 East 5th Street Wauneta, Nebraska 69033

US. Coast Guard Finance Center (OGR) 1430A Kristina Way Chesapeake, VA 23326

Dated: 12/12/03

Kathy Robinson

Regional Hearing Clerk